

## **SULFATE ATTACK OF PORTLAND CEMENT**

S.R. Stock<sup>1,\*</sup>, K. Ignatiev<sup>1</sup>, A.P. Wilkinson<sup>2</sup>, N. Naik<sup>3</sup> and K.E. Kurtis<sup>3</sup>

Schools of <sup>1</sup>Materials Sci. & Eng., <sup>2</sup>Chemistry & Biochemistry and

<sup>3</sup>Civil & Environmental Eng., Georgia Inst. of Technology, Atlanta, GA, USA

\*On leave at Inst. for Bioengineering & Nanoscience in Advanced Medicine,  
Northwestern Univ., Chicago, IL, USA

Attack of Portland cement by ambient sulfates presents a considerable risk to structures in some environments. In this study, x-ray microtomography, a high resolution variant of medical “CT”, noninvasively maps cracking in Portland cement resulting from exposure to aqueous solutions containing sulfates; and x-ray diffractometry reveals the reaction products associated with the three-dimensional network of cracks.